

# EXHIBIT A

# **EXHIBIT A-1**

## Reliability Project Cover Sheet

P.I Name	<span style="background-color: black; color: black;">[REDACTED]</span>	Customer Affected:	102
Project Name/SSD	girvan 1101 ssd 1861	Forecast Completion Date:	5/15/2016
Location	Igo	Forecast Units:	40
Routine Schedule Date		Tree Wire: (approximate %)	no
PI	start date 6/22/15	Line Miles	4
TT	start date 7/22/15	Concurrent Patrol (yes/no)	no

PS&amp;R Schedule Date (Previous Project)

TT compl. date \_\_\_\_ n/a \_\_\_\_

# of units \_\_\_\_ n/a \_\_\_\_

**Summary of Outage History:**

Date	Species	Type of Failure (root, branch or trunk)	Height & DBH
3/28/2011	gray pine	uproot	100/23
7/22/2014	valley oak	uproot	70/45

general terrain: Rolling hills pasture/agricultural

Local Issues: several ic customers on Zogg mine rd

Agencies: n/a

Safety Issues: narrow roads

CNDDB: Riparian areas

Other Factors:

# **EXHIBIT A-2**

### TailBoard Checklist

Project Name: GIRVAN 1101 SSD 1861		Date: 5/2/16	
Address & Loc. Route#	Issue	Issue Details:	Tailboard done Y/N
101020-10-50	ACCESS	POSSIBLE LA IF DRY W/SMALL 4X4, ACCESS FLGD GATE N/OF [REDACTED] E/SIDE OF RD WALK IN ACCESS AT GATE ON SOTH FORK RD BY SSD	
101020-60	ACCESS/NOTE	VERY OM VALLEY OAK W/SUBSTANTIAL OV, POSSIBLE LA FROM N/SIDE OF FENCE FROM [REDACTED] IF DRY MAY REQUIRE LINE KILL	
101020-70-80	ACCESS	POSSIBLE LA @ FLAGGED RD .4 MI. N/OF ADDRESS [REDACTED] OR AT POSTED ADD. CONTACT OWNER FOR ACCESS INFO.	
101020-90-97	ACCESS	AXS FLGD RD .4 MI. N/ OF ADDRESS [REDACTED], FOLLOW FLGD TRAIL W/OF ARROW ON TREE @ CULVERT N/TO P31 AXS TRAIL N/OF P32 X-FENCE/CREEK TO LOC 97, OAKS W/OV MAY REQUIRE LINE KILL	
101020-130-160	ACCESS	ALTERNATE ACCES, FOLLOW LINES CROSS CREEK BEHIND HOUSE AT END OF RD	
101020-200	ACCESS	GATE MAY NOT BE FLAGGED AS UNKNOWN PARTY HAS REMOVED FLAGGING PREVIOUSLY MAY BE TOO DRY FOR LA. CONTACT [REDACTED] FOR GATE ACCESS.	

Is there any special notification needed for this project?

- ☐ Government Relations
- ☐ Media
- ☐ Customer Impact
- ☐ PG&E Program Manager(s)
- ☐ Agency
- ☐ Customer

Have all T&amp;M Requests been identified, submitted and pre-approved?

- ☐ YES
- ☐ NO


PI Signature:

[REDACTED]

Tree Crew Signature:


[REDACTED]

# **EXHIBIT A-3**




# **EXHIBIT A-4**







# **EXHIBIT A-5**



# **EXHIBIT A-6**



# **EXHIBIT A-7**



# **EXHIBIT A-8**



**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				<b>I</b> <b>ector / Company:</b> - CNU			
<b>Division:</b> North Valley	<b>Circuit: (0103401101)</b> GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 110	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/4/2016 1:41:53 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870621	<b>hone:</b>				
<b>Comment:</b> AXS LINE XING .4 MI. N/OF P2 IN FIELD E/OF RD P8 6S/W OWNER @ END OF RD													
									<b>Audit</b>		<i>Last Edit: 5/17/2016 12:44:24 PM by:</i>		
<b>Tree Number</b>  1	<b>Tree Species:</b> Gray Pine	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 70 18	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Trim B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/4/2016 1:42:24 PM
	<b>Comment:</b> .7S W/OF P8 S/OF LINES					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/9/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FBB	<b>Completed By:</b>	<b>Invoice:</b> BB (104)
	<b>Lat/Long:</b> 40.518716667, -122.57194 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>Audit</b>		<b>Last Edit:</b> 5/6/2016 by:
	<b>Rx Comment:</b> REMOVE LINE SIDE LEAD POOR ATTACHMENT												

# **EXHIBIT A-9**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				<b>I</b> <b>ctor / Company:</b> - CNU			
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 80	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/2/2016 2:54:02 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870620	<b>mer Name/Phone:</b>				
<b>Comment:</b> AXS LINE XING .4 MI. N/OF P29 TP 2S/E P27 3S/S													
									<b>Audit</b>		<i>Last Edit: 6/7/2016 1:36:36 PM by:</i>		
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 80 50	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/2/2016 3:14:03 PM
	<b>Comment:</b> .3S/N/OF P27 XSTMTRIM 2 SKY					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/22/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FOB	<b>Completed By:</b>	<b>Invoice:</b> BO (104)
	<b>Lat/Long:</b> 40.511716667, -122.568665 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>Audit</b>	<b>Last Edit:</b> 5/2/2016 by:	
	<b>Rx Comment:</b> POS LA												

# **EXHIBIT A-10**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>				<b>City:</b> IGO		<b>County:</b> SH		<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				<b>I</b> <b>ector / Company:</b> - CNU	
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 70	<b>(none):</b>			<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>			
<b>Insp Date / Time:</b> 5/2/2016 3:16:37 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>			<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870620	<b>mer Name/Phone:</b>			
<b>Comment:</b> AXS LINE XING .4 MI. N/OF P29 TP 2S/E P26 3S/S													
										<b>  Audit  </b>		<i>Last Edit: 6/7/2016 1:36:13 PM by:</i>	
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height</b> <b>DBH</b> <b>Clearance</b> <b>Prox:</b> 100 48 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/2/2016 3:17:54 PM	
	<b>Comment:</b> @P26					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523	<b>WC Date:</b> 8/15/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FOB	<b>Completed By:</b>	<b>Invoice:</b> BO (104)	
	<b>Lat/Long:</b> 40.511718333, -122.568666667 <a href="#">Google Map!</a>					<b>External TreeID:</b>					<b>  Audit  </b>	<b>Last Edit:</b> 5/2/2016 by:	
	<b>Rx Comment:</b> TRIM LONG LIMB ON N/SIDE BACK TO 90 DEG. UNION												

# **EXHIBIT A-11**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>				<b>City:</b> IGO		<b>County:</b> SH		<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ZOGG MINE RD				<b>I</b> <b>ctor / Company:</b> - CNU	
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 180	<b>(none):</b>			<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b> AX			
<b>Insp Date / Time:</b> 5/9/2016 10:13:34 AM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>			<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b>	<b>ne:</b>			
<b>Comment:</b> P44 SSD 4191 RDSN N/OF ADD @ FLGD GATE P45 AP 1S/NE OWNER IN WA STATE													
												<b>Audit</b>	<b>Last Edit:</b> 6/14/2016 11:27:47 AM by:
<b>Tree Number</b>  1	<b>Tree Species:</b> Live Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 65 24	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Major B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 6/10/2016 11:20:10 AM
	<b>Comment:</b> .3S NE/OF P45 AP E/OF LINES					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/22/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FBB	<b>Completed By:</b>	<b>Invoice:</b> BB (104)
	<b>Lat/Long:</b> 40.528438333, -122.556696667 <a href="#">Google Map!</a>					<b>External TreeID:</b>					<b>Audit</b>	<b>Last Edit:</b> 6/10/2016 by:	
	<b>Rx Comment:</b> ROT/WIND EXPOSURE												
<b>Tree Number</b>  2	<b>Tree Species:</b> Gray Pine	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 100 42	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Major B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/9/2016 10 AM
	<b>Comment:</b> .8S NE/OF P45 AP E/OF LINES					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 10/26/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FBB	<b>C mpleted By:</b>	<b>Invoice:</b> BB (104)
	<b>Lat/Long:</b> 40.529288333, -122.556578333 <a href="#">Google Map!</a>					<b>External TreeID:</b>					<b>Audit</b>	<b>Last Edit:</b> 5/9/2016 by:	
	<b>Rx Comment:</b>												

# **EXHIBIT A-12**



**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>				<b>City:</b> IGO	<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD.>N/ON ARCHER RD				<b>I</b> <b>ctor / Company:</b> - CNU				
<b>Division:</b> North Valley	<b>Circuit: (0103401101)</b> GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 95	<b>(none):</b>				<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>			
<b>Insp Date / Time:</b> 5/10/2016 8:55:38 AM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>			<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870620	<b>C</b> <b>mer Name/Phone:</b>				
<b>Comment:</b> AXS LINE XING .4 MI. N/OF P29 TP 2S/E P32 3S/N														
										<b>  Audit  </b>		<b>Last Edit: 5/17/2016 10:49:47 AM by:</b>		
<b>Tree Number</b>  1	<b>Tree Species:</b> Gray Pine	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 100 23	<b>Clearance Prox:</b> 9 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Rmv2 B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/10/2016 8:56:49 AM	
	<b>Comment:</b> .2S N/OF P32 80' W/OF LIINES					<b>Notification:</b> OK		<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/12/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FBB	<b>Completed By:</b>	<b>Invoice:</b> BB (104)
	<b>Lat/Long:</b> 40.52065, -122.562376667 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>  Audit  </b>		<b>Last Edit:</b> 5/10/2016 by:	
	<b>Rx Comment:</b>													
<b>Tree Number</b>  2	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 85 24	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 2	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/10/2016 9 AM	
	<b>Comment:</b> 5S N/OF P32 W/OF LIINES AVG DBH/HT					<b>Notification:</b> OK		<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/11/2016	<b>WC Qty:</b> 2	<b>WC Trim:</b> FBB	<b>C mpleted By:</b>	<b>Invoice:</b> BB (104)
	<b>Lat/Long:</b> 40.520998333, -122.562173333 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>  Audit  </b>		<b>Last Edit:</b> 5/10/2016 by:	
	<b>Rx Comment:</b>													

# **EXHIBIT A-13**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>				<b>City:</b> IGO		<b>County:</b> SH		<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				<b>I</b> <b>ctor / Company:</b> - CNU	
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 97	<b>(none):</b>			<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>			
<b>Insp Date / Time:</b> 5/10/2016 9:38:27 AM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>			<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 28259833	<b>er Name/Phone:</b>			
<b>Comment:</b> AXS LINE XING .4 MI. N/OF P29 TP 2S/E P32 3S/N													
										<b>Audit</b>		<i>Last Edit: 5/20/2016 8:02:08 AM by:</i>	
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 95 35	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/10/2016 9:38:54 AM
	<b>Comment:</b> .7S N/OF P32 X-CREEK W/OF LINES					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/11/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FOB	<b>Completed By:</b>	<b>Invoice:</b> BO (104)
	<b>Lat/Long:</b> 40.521378333, -122.562008333 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>Audit</b>	<b>Last Edit:</b> 5/10/2016 by:	
	<b>Rx Comment:</b>												

# **EXHIBIT A-14**

Cust.Inf. | MAP | History

## Inspection Record Detail

A			City:	County:	Directions:			Inspector / Company:						
			IGO	SH	W/ON PLACER RD>NW/ON SOUTH FORK RD			- CNU						
Division:	Circuit: (0103401101)	SSD #:	SSD Rte #:	Routing #:	(none):	Area:	SRA	Alerts:						
North Valley	GIRVAN 1101	1861	101020	10			Yes							
Insp Date / Time:	Tag Type:	Tag Number:	Line Name:		Pole Num:	Quad Map:	Removal #:	Crewer Name/Phone:						
5/2/2016 10:10:01 AM	Reliability	137636												
Comment:														
P0 SSD 1861 RDSD A/F P1 1S/N														
<a href="#">Audit</a>   Last Edit 5/20/2016 7:38:44 AM by														
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:	
1	Gray Pine	CA	Routine	No	Private	70 18	99 Inside	Rtn	2	FP-Rmv2 B	Y		5/2/2016 11:02:51 AM	
	Comment:				Notification:	Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice:		
	.1S N/OF P1 E/OF LINES AVG DBH/HT				OK	YSNV1000523		8/4/2016	2	F2B		B2 (104)		
	Lat/Long:				External TreeID:				<a href="#">Audit</a>   Last Edit:		5/2/2016 by			
Rx Comment:														
LEAN														
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:	
2	Gray Pine	CA	Routine	No	Private	70 39	99 Inside	Rtn	1	FP-Rmv4 B	Y		5/2/2016 11:02:51 AM	
	Comment:				Notification:	Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice:		
	.5S N/OF P1 E/OF LINES XSTM				OK	YSNV1000523		8/4/2016	1	F4B		B4 (104)		
	Lat/Long:				External TreeID:				<a href="#">Audit</a>   Last Edit:		5/2/2016 by			
Rx Comment:														
LEAN														
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:	
3	Gray Pine	CA	Routine	No	Private	80 19	99 Inside	Rtn	2	FP-Rmv2 B	Y		5/2/2016 11:18:01 AM	
	Comment:				Notification:	Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice:		
	.5S N/OF P1 E/OF LINES AVG DBH/HT				OK	YSNV1000523		8/2/2016	2	F2B		B2 (104)		
	Lat/Long:				External TreeID:				<a href="#">Audit</a>   Last Edit:		5/2/2016 by			
Rx Comment:														
LEAN														
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:	
4	Gray Pine	CA	Routine	No	Private	80 15	99 Inside	Rtn	1	FP-Rmv2 B	Y		5/2/2016 11:02:51 AM	
	Comment:				Notification:	Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice:		
	.9S N/OF P1 W/OF LINES				OK	YSNV1000523		8/2/2016	1	F2B		B2 (104)		
	Lat/Long:				External TreeID:				<a href="#">Audit</a>   Last Edit:		5/2/2016 by			
Rx Comment:														
LEAN														

# **EXHIBIT A-15**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>				<b>City:</b> IGO		<b>County:</b> SH		<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ZOGG MINE RD				<b>I</b> <b>ector / Company:</b> - CNU															
<b>Division:</b> North Valley		<b>Circuit: (0103401101)</b> GIRVAN 1101		<b>SSD #:</b> 1861		<b>SSD Rte #:</b> 101020		<b>Routing #:</b> 200		<b>(none):</b>		<b>Area:</b>		<b>SRA</b> Yes		<b>Alerts:</b> AX											
<b>Insp Date / Time:</b> 5/9/2016 11:37:09 AM			<b>Tag Type:</b> Reliability		<b>Tag Number:</b> 137636		<b>Line Name:</b>				<b>Pole Num:</b>		<b>Quad Map:</b>		<b>Removal #:</b> 3870777		<b>C</b> <b>hone:</b>										
<b>Comment:</b> P44 SSD 4191 RDSN N/OF ADD @ FLGD GATE P43 1S/SW OWNER @																											
																<b>  Audit  </b>		<b>Last Edit: 6/14/2016 11:18:09 AM by:</b>									
<b>Tree Number</b>		<b>Tree Species:</b> Gray Pine		<b>Crew:</b> CA		<b>Priority:</b> Routine		<b>TGR:</b> No		<b>Owned By:</b> Private		<b>Height DBH</b> 80 23		<b>Clearance Prox:</b> 99 Inside		<b>Cycle:</b> Rtn		<b>Qty:</b> 1		<b>Trim Type:</b> FP-Rmv2 B		<b>Account:</b> Y		<b>Wire Conditions:</b>		<b>Insp Date:</b> 5/9/2016 11:38:16 AM	
1		<b>Comment:</b> .7S/SW OF P43 W/OF LINES FLGD X-FENCE										<b>Notification:</b> OK		<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/22/2016		<b>WC Qty:</b> 1		<b>WC Trim:</b> F2B		<b>Completed By:</b>		<b>Invoice:</b> B2 (104)			
		<b>Lat/Long:</b> 40.52682, -122.55797 <a href="#">Google Map!</a>						<b>External TreeID:</b>								<b>  Audit  </b>		<b>Last Edit:</b> 5/18/2016 by:									
		<b>Rx Comment:</b> LEAN																									
<b>Tree Number</b>		<b>Tree Species:</b> Gray Pine		<b>Crew:</b> CA		<b>Priority:</b> Routine		<b>TGR:</b> No		<b>Owned By:</b> Private		<b>Height DBH</b> 70 18		<b>Clearance Prox:</b> Inside		<b>Cycle:</b> Rtn		<b>Qty:</b> 1		<b>Trim Type:</b> FP-Rmv2 B		<b>Account:</b> Y		<b>Wire Conditions:</b>		<b>Insp Date:</b> 6/10/2016 1 AM	
2		<b>Comment:</b> .8S/SW OF P43 W/OF LINES										<b>Notification:</b> OK		<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/22/2016		<b>WC Qty:</b> 1		<b>WC Trim:</b> F2B		<b>C</b> <b>eted By:</b>		<b>Invoice:</b> B2 (104)			
		<b>Lat/Long:</b> 40.526708333, -122.558048333 <a href="#">Google Map!</a>						<b>External TreeID:</b>								<b>  Audit  </b>		<b>Last Edit:</b> 6/10/2016 by:									
		<b>Rx Comment:</b> DAMAGE AT BASE FROM FENCE																									

# **EXHIBIT A-16**



**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD.>N/ON ARCHER RD			<b>Inspector / Company:</b> [REDACTED] - CNU						
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 140	<b>(none):</b>			<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>					
<b>Insp Date / Time:</b> 5/6/2016 12:09:50 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>			<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870621	<b>hone:</b> [REDACTED]					
<b>Comment:</b> AXS LINE XING .4 MI. N/OF [REDACTED] P2 IN FIELD E/OF RD P16 14S/W OWNER @ END OF RD															
										<b>Audit</b>	<b>Last Edit:</b> 6/8/2016 1:28:52 PM by: [REDACTED]				
<b>Tree Number</b>  1	<b>Tree Species:</b> Black Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height</b> 70	<b>DBH</b> 30	<b>Clearance</b> 99	<b>Prox:</b> Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FS-R3A+Trt	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> [REDACTED] 5/6/2016 12:10:53 PM
	<b>Comment:</b> .5S/NW OF F16					<b>Notification:</b> OK		<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/10/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> F3C	<b>Completed By:</b> [REDACTED]	<b>Invoice:</b> C3 (104)	
	<b>Lat/Long:</b> 40.51984, -122.576781667 <a href="#">Google Map!</a>					<b>External TreeID:</b>							<b>Audit</b>	<b>Last Edit:</b> 5/6/2016 by: [REDACTED]	
	<b>Rx Comment:</b>														

# **EXHIBIT A-17**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD.>N/ON ARCHER RD			<b>Inspector / Company:</b> [REDACTED] - CNU				
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 160	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/6/2016 12:28:55 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870621	<b>hone:</b> [REDACTED]				
<b>Comment:</b> AXS LINE XING .4 MI. N/OF [REDACTED] P2 IN FIELD E/OF RD P18 16S/W OWNER @ END OF RD													
									<b>Audit</b>		<b>Last Edit:</b> 5/17/2016 12:46:45 PM by: [REDACTED]		
<b>Tree Number</b>  1	<b>Tree Species:</b> Black Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 60 12	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FS-R2A+Trt	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/6/2016 12:29:42 PM
	<b>Comment:</b> .2S NW OFP18					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/10/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> F2C	<b>Completed By:</b> [REDACTED]	<b>Invoice:</b> C2 (104)
	<b>Lat/Long:</b> 40.521013333, -122.577696667 <a href="#">Google Map!</a>					<b>External TreeID:</b>					<b>Audit</b>	<b>Last Edit:</b> 5/6/2016 by: [REDACTED]	
	<b>Rx Comment:</b>												

# **EXHIBIT A-18**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

A			City: IGO		County: SH	Directions: W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				Inspector / Company: [REDACTED] - CNU			
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 1861	SSD Rte #: 101020	Routing #: 100	(none):		Area:	SRA Yes	Alerts:				
Insp Date / Time: 5/3/2016 2:58:38 PM	Tag Type: Reliability	Tag Number: 137636	Line Name:			Pole Num:	Quad Map:	Removal #:	/Phone: [REDACTED]				
Comment: AXS LINE XING .4 MI. N/OF [REDACTED] P2 IN FIELD E/OF RD													
									Audit		Last Edit: 5/3/2016 3:35:15 PM by: [REDACTED]		
Tree Number  1	Tree Species: Gray Pine	Crew: CA	Priority: Routine	TGR: No	Owned By: Private	Height DBH 80 24	Clearance Prox: 99 Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Ov A	Account: Y	Wire Conditions:	Insp Date: 5/3/2016 3:00:07 PM
	Comment: .8S W/OF P2 N/OF LINES					Notification: OK		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:
	Lat/Long: 40.518056667, -122.56593 <a href="#">Google Map!</a>					External TreeID:					Audit		Last Edit: 5/3/2016 by: [REDACTED]
	Rx Comment: POS LA												

# **EXHIBIT A-19**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD			<b>I</b> <b>ector / Company:</b> - CNU				
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 130	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/6/2016 11:53:59 AM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870621	<b>C</b> <b>hone:</b>				
<b>Comment:</b> AXS LINE XING .4 MI. N/OF P2 IN FIELD E/OF RD P14 12S/W OWNER @ END OF RD													
									<b>Audit</b>		<b>Last Edit:</b> 5/17/2016 12:43:25 PM by:		
<b>Tree Number</b>  1	<b>Tree Species:</b> Gray Pine	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 70 24	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Rmv3 A	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/6/2016 11:54:58 AM
	<b>Comment:</b> .5S W/OF P14 N/OFLINES					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/9/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> F3A	<b>Completed By:</b>	<b>Invoice:</b> A3 (104)
	<b>Lat/Long:</b> 40.51924, -122.576516667 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>Audit</b>	<b>Last Edit:</b> 5/6/2016 by:	
	<b>Rx Comment:</b> MULTIPLE CO-DOMS W/INCLUDED BARK												

# **EXHIBIT A-20**



**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

A			City: IGO		County: SH	Directions: W/ON PLACER RD>NW/ON SOUTH FORK RD			Inspector / Company: - CNU				
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 1861	SSD Rte #: 101020	Routing #: 40	(none):		Area:	SRA Yes	Alerts:				
Insp Date / Time: 5/2/2016 11:55:33 AM	Tag Type: Reliability	Tag Number: 137636	Line Name:			Pole Num:	Quad Map:	Removal #: 28281527	Inspector Name/Phone: [REDACTED]				
Comment: P0 SSD 1861 RDSD A/F [REDACTED] P5 5S/N													
									Audit		Last Edit 5/20/2016 7 42 04 AM by [REDACTED]		
Tree Number  1	Tree Species: Valley Oak	Crew: CA	Priority: Routine	TGR: No	Owned By: Private	Height DBH 80 17	Clearance Prox: 99 Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Trim B	Account: Y	Wire Conditions:	Insp Date: [REDACTED] 5/2/2016 11:56:27 AM
	Comment: .7S N/OF P5 E/OF LINES TBL					Notification: OK	Work Request: Y5NV1000523		WC Date: 8/8/2016	WC Qty: 1	WC Trim: FBB	Completed By: [REDACTED]	Invoice: BB (104)
	Lat/Long: 40.504856667, -122.570098333 <a href="#">Google Map!</a>					External TreeID:					Audit		Last Edit: 5/2/2016 by [REDACTED]
	Rx Comment:												

# **EXHIBIT A-21**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH		<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD				<b>I</b> <b>ctor / Company:</b> - CNU		
<b>Division:</b> North Valley	<b>Circuit: (0103401101)</b> GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 20	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/2/2016 11:08:59 AM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>			<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b>	<b>er Name/Phone:</b>			
<b>Comment:</b> P0 SSD 1861 RDSD A/F P2 2S/N													
										<b>Audit</b>		<i>Last Edit: 5/20/2016 7:40:48 AM by:</i>	
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 80 18	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/2/2016 11:29:22 AM
	<b>Comment:</b> .6SN/OF P2 W/OF LINES TRIM 2 SKY					<b>Notification:</b> OK		<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/2/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FBB	<b>Completed By:</b> BB (104)
	<b>Lat/Long:</b> 40.502761667, -122.569971667 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>Audit</b>		<b>Last Edit:</b> 6/7/2016 by:
	<b>Rx Comment:</b> FP OV												

# **EXHIBIT A-22**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				<b>I</b> <b>ector / Company:</b> - CNU			
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 120	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/4/2016 1:48:46 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870621	<b>hone:</b>				
<b>Comment:</b> AXS LINE XING .4 MI. N/OF P2 IN FIELD E/OF RD P9 7S/W OWNER @ END OF RD													
									<b>Audit</b>		<i>Last Edit: 5/17/2016 12:45:13 PM by:</i>		
<b>Tree Number</b>  1	<b>Tree Species:</b> Gray Pine	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 80 10	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Trim B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/4/2016 1:50:58 PM
	<b>Comment:</b> .4S W/OF P9 N/OF LINES FLGD IFO					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/9/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FBB	<b>Completed By:</b>	<b>Invoice:</b> BB (104)
	<b>Lat/Long:</b> 40.518836667, -122.572278333 <a href="#">Google Map!</a>					<b>External TreeID:</b>					<b>Audit</b>		<b>Last Edit:</b> 5/4/2016 by:
	<b>Rx Comment:</b> REMOVE LINE SIDE LEAD POOR ATTACHMENT												

# **EXHIBIT A-23**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				<b>I</b> <b>ector / Company:</b> - CNU			
<b>Division:</b> North Valley	<b>Circuit: (0103401101)</b> GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 60	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/2/2016 1:17:45 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870620	<b>mer Name/Phone:</b>				
<b>Comment:</b> AXS EP RDSD N/OF P7 TP 2S/E AXS GATE N/OF ADD ON E/SD OF RD OWNER @													
									<b>Audit</b>	<i>Last Edit: 5/17/2016 10:47:27 AM by:</i>			
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 100 36	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/2/2016 1:50:28 PM
	<b>Comment:</b> .9S N/OF P7 TP E/OF LINES TRIM 2 SKY					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/22/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FOB	<b>Completed By:</b>	<b>Invoice:</b> BO (104)
	<b>Lat/Long:</b> 40.506345, -122.5703 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>Audit</b>	<b>Last Edit:</b> 5/2/2016 by:	
	<b>Rx Comment:</b> OM/OV												

# **EXHIBIT A-24**



**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

A				City: IGO		County: SH		Directions: W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				Inspector / Company: - CNU	
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 1861	SSD Rte #: 101020	Routing #: 165	(none):			Area:	SRA Yes	Alerts:			
Insp Date / Time: 5/12/2016 12:35:51 PM	Tag Type: Reliability	Tag Number: 137636	Line Name:			Pole Num:	Quad Map:	Removal #:	mer Name/Phone: -??-??-???				
Comment: EP IFO HOUSE END OF DVWY													
												Audit	Last Edit: 5/17/2016 11:56:18 AM by:
Tree Number  1	Tree Species: Gray Pine	Crew: LA	Priority: Routine	TGR: No	Owned By: Private	Height DBH 80 24	Clearance Prox: 99 Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Ov A	Account: Y	Wire Conditions:	Insp Date: ( ) 5/12/2016 12:37:59 PM
	Comment: .9S S/OF EP					Notification: OK	Work Request:	WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice: Not Worked	
	Lat/Long: 40.513971667, -122.572653333 <a href="#">Google Map!</a>					External TreeID:				Audit	Last Edit: 5/12/2016 by:		
	Rx Comment:												

# **EXHIBIT A-25**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD.>N/ON ARCHER RD			<b>Inspector / Company:</b> [REDACTED] - CNU				
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 150	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/6/2016 12:21:32 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870621	<b>hone:</b> [REDACTED]				
<b>Comment:</b> AXS LINE XING .4 MI. N/OF [REDACTED] P2 IN FIELD E/OF RD P17 15S/W OWNER @ END OF RD													
									<b>Audit</b>		<b>Last Edit:</b> 6/8/2016 1:28:34 PM by: [REDACTED]		
<b>Tree Number</b>  1	<b>Tree Species:</b> Black Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 60 20	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FS-R2A+Trt	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> [REDACTED] 5/6/2016 12:23:17 PM
	<b>Comment:</b> .6S NW/OF P17					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/10/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> F2C	<b>Completed By:</b> [REDACTED]	<b>Invoice:</b> C2 (104)
	<b>Lat/Long:</b> 40.520573333, -122.577588333 <a href="#">Google Map!</a>				<b>External TreeID:</b>						<b>Audit</b>	<b>Last Edit:</b> 5/6/2016 by: [REDACTED]	
	<b>Rx Comment:</b>												

# **EXHIBIT A-26**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>				<b>City:</b> IGO		<b>County:</b> SH		<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ZOGG MINE RD				<b>I</b> <b>ector / Company:</b> - CNU			
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 190	<b>(none):</b>			<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b> TR					
<b>Insp Date / Time:</b> 5/9/2016 10:49:32 AM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>			<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b>	<b>ne:</b>					
<b>Comment:</b> P44 SSD 4191 RDSD N/OF ADD @ FLGD GATE P47 3S/NE OWNER IN WA STATE															
										<b>Audit</b>		<i>Last Edit: 6/14/2016 11:26:58 AM by:</i>			
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> LA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height</b>	<b>DBH</b>	<b>Clearance</b>	<b>Prox:</b>	<b>Cycle:</b>	<b>Qty:</b>	<b>Trim Type:</b>	<b>Account:</b>	<b>Wire Conditions:</b>	<b>Insp Date:</b>
	<b>Comment:</b> RDSD.3S/NEOF P47					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/22/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FOB	<b>Completed By:</b>	<b>Invoice:</b> BO (104)		
	<b>Lat/Long:</b> 40.530848333, -122.556485 <a href="#">Google Map!</a>					<b>External TreeID:</b>						<b>Audit</b>	<b>Last Edit:</b> 5/9/2016 by:		
	<b>Rx Comment:</b> TRIM STEM ON SE/SIDE BACK TO LARGE WOOD														

# **EXHIBIT A-27**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD				<b>I</b> <b>ector / Company:</b> - CNU			
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 30	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/2/2016 11:35:57 AM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b>	<b>er Name/Phone:</b>				
<b>Comment:</b> P0 SSD 1861 RDSD A/F P4 IDLE TP 4S/N													
									<b>Audit</b>		<i>Last Edit: 5/20/2016 7:41:27 AM by:</i>		
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 80 25	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Trim B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/2/2016 11:36:57 AM
	<b>Comment:</b> .2S/N OF P4					<b>Notification:</b> OK	<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/8/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FAB	<b>Completed By:</b>	<b>Invoice:</b> BA (104)
	<b>Lat/Long:</b> 40.503618333, -122.570021667 <u>Google Map!</u>				<b>External TreeID:</b>					<b>Audit</b>		<b>Last Edit:</b> 5/2/2016 by:	
	<b>Rx Comment:</b> TRIM NORTHERN MOST LIMB BACK TO BIG WOOD												

# **EXHIBIT A-28**



**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>				<b>City:</b> IGO		<b>County:</b> SH		<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD>N/ON ARCHER RD				<b>Inspector / Company:</b> [REDACTED] - CNU		
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 90	<b>(none):</b>			<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/3/2016 10:49:01 AM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>			<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870620	<b>Inspector Name/Phone:</b> [REDACTED]				
<b>Comment:</b> AXS LINE XING .4 MI. N/OF [REDACTED] P29 TP 2S/E P31 2/SN														
										<b>Audit</b>		<b>Last Edit:</b> 5/16/2016 8:43:10 AM by: [REDACTED]		
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 75 20	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/3/2016 11:43:25 AM	
	<b>Comment:</b> .5S/N OF P31 E/OF LINES FLGD IFO					<b>Notification:</b> OK		<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/12/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FOB	<b>Completed By:</b> [REDACTED]	<b>Invoice:</b> BO (104)
	<b>Lat/Long:</b> 40.519928333, -122.562916667 <a href="#">Google Map!</a>					<b>External TreeID:</b>						<b>Audit</b>	<b>Last Edit:</b> 5/3/2016 by: [REDACTED]	
	<b>Rx Comment:</b> SNOW LOADER													
<b>Tree Number</b>  2	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 80 40	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/3/2016 11:43:25 AM	
	<b>Comment:</b> .7S/N OF P31 W/OF LINES					<b>Notification:</b> OK		<b>Work Request:</b> YSNV1000523		<b>WC Date:</b> 8/22/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FOB	<b>Completed By:</b> [REDACTED]	<b>Invoice:</b> BO (104)
	<b>Lat/Long:</b> 40.520123333, -122.562798333 <a href="#">Google Map!</a>					<b>External TreeID:</b>						<b>Audit</b>	<b>Last Edit:</b> 5/3/2016 by: [REDACTED]	
	<b>Rx Comment:</b> TRIM 2 SKY													

# **EXHIBIT A-29**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

[REDACTED]			City: IGO		County: SH	Directions: W/ON PLACER RD>NW/ON SOUTH FORK RD.>N/ON ZOGG MINE RD			Inspector / Company: [REDACTED] - CNU				
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 1861	SSD Rte #: 101020	Routing #: 170	(none):			Area:	SRA Yes	Alerts:			
Insp Date / Time: 5/9/2016 9:45:18 AM	Tag Type: Reliability	Tag Number: 137636	Line Name:			Pole Num:	Quad Map:	Removal #:	Customer Name/Phone:				
Comment: P44 SSD 4191 RDSD N/OF ADD [REDACTED] @ FLGD GATE													
									Audit		Last Edit: 6/9/2016 2:57:30 PM by: [REDACTED]		
Tree Number  1	Tree Species: Gray Pine	Crew: LA	Priority: Routine	TGR: No	Owned By: Private	Height DBH 75 19	Clearance Prox: 99 Inside	Cycle:	Qty: 1	Trim Type: FP-Rmv2 B	Account: Y	Wire Conditions:	Insp Date: 5/9/2016 9:49:35 AM
	Comment: .5S N/OF P44 W/SD OF RD FLGD IFO					Notification: Contact		Work Request:	WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice: Not Worked
	Lat/Long: 40.52798, -122.55719 <a href="#">Google Map!</a>				External TreeID:						Audit		Last Edit: 5/9/2016 by: [REDACTED]
	Rx Comment: LEAN/MULTIPLE BOLE DEFECTS @BASE												

# **EXHIBIT A-30**

**Search** **Print****North Valley Division - Distribution (YS - 137636)****Work Request:** YSNV1000523**Contractor:** Davey Tree- Sent to Contractor. **Order No:** 8082293**Date Issued:** 6/15/2016 4:03:40 PM**Completed:** 8/4/2016 By: [REDACTED]

[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
1.) 2 FP-R2	2 FP-R2	8/4/16	By: [REDACTED]	<u>r</u>	Invoiced
2.) 1 FP-R4	1 FP-R4	8/4/16	By: [REDACTED]	<u>r</u>	Invoiced
3.) 2 FP-R2	2 FP-R2	8/2/16	By: [REDACTED]	<u>r</u>	Invoiced
4.) 1 FP-R2	1 FP-R2	8/2/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
5.) 1 FP-Ov	1 <b>FP-Tr !</b>	8/2/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
6.) 1 FP-Tr	1 FP-Tr	8/8/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
7.) 1 FP-Tr	1 <b>FP-Tr !</b>	8/8/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
8.) 1 FP-Ov	1 FP-Ov	8/22/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
9.) 1 FP-Ov	1 FP-Ov	8/15/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
10.) 1 FP-Ov	1 FP-Ov	8/22/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
11.) 1 FP-Ov	1 FP-Ov (OT)	8/12/16	By: [REDACTED]	<u>r</u>	Invoiced
12.) 1 FP-Ov	1 FP-Ov	8/22/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
13.) 1 FP-R2	1 <b>FP-Tr ! (OT)</b>	8/12/16	By: [REDACTED]	<u>r</u>	Invoiced
14.) 2 FP-Ov	2 <b>FP-Tr !</b>	8/11/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
15.) 1 FP-Ov	1 FP-Ov	8/11/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
16.) 1 FP-Tr	1 <b>FP-Tr !</b>	8/9/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
17.) 1 FP-Tr	1 <b>FP-Tr !</b>	8/9/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
18.) 1 FP-R3	1 FP-R3	8/9/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
19.) 1 FP-R3	1 FP-R3	8/10/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
20.) 1 FP-R2	1 FP-R2	8/10/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
21.) 1 FP-R2	1 FP-R2	8/10/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
22.) 1 FP-Tr	1 FP-Tr	8/22/16	By: [REDACTED]	<u>r</u>	Invoiced
23.) 1 FP-Tr	1 FP-Tr	10/26/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
24.) 1 FP-Ov	1 <b>FP-Ov !</b>	8/22/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
25.) 1 FP-R2	1 FP-R2	8/22/16	By: [REDACTED]	<u>r</u>	Invoiced
26.) 1 FP-R2	1 FP-R2	8/22/16	By: [REDACTED]	<u>r</u>	Invoiced
[REDACTED] ...		Circuit: GIRVAN 1101 - (0103401101)			
27.) - Added -	1 <b>FP-Tr !</b>	8/9/16	By: [REDACTED]	<u>r</u>	Invoiced
28.) - Added -	5 <b>FP-Tr !</b>	8/15/16	By: [REDACTED]	<u>r</u>	Invoiced
29.) - Added -	2 <b>FP-Tr !</b>	8/8/16	By: [REDACTED]	<u>r</u>	Invoiced

**Units Assigned: 29.0**

**Units Completed: 37.0 - ( 127.6% )**

<p><b>!</b> - Indicates that some of the work completed is different than what was assigned.</p> <p><b>r</b> - Revised. Record has been billed and then updated by contractor.</p>
--



PG&E Vegetation Management - VMS Database.

This Report was created on: 3/2/2021 9:04:54 AM.

# **EXHIBIT A-31**

**Cust.Inf.** | **MAP** | **History**

**Inspection Record Detail**

<b>A</b>			<b>City:</b> IGO		<b>County:</b> SH	<b>Directions:</b> W/ON PLACER RD>NW/ON SOUTH FORK RD				<b>I</b> <b>ector / Company:</b> - CNU			
<b>Division:</b> North Valley	<b>Circuit:</b> (0103401101) GIRVAN 1101	<b>SSD #:</b> 1861	<b>SSD Rte #:</b> 101020	<b>Routing #:</b> 50	<b>(none):</b>		<b>Area:</b>	<b>SRA</b> Yes	<b>Alerts:</b>				
<b>Insp Date / Time:</b> 5/2/2016 12:00:41 PM		<b>Tag Type:</b> Reliability	<b>Tag Number:</b> 137636	<b>Line Name:</b>		<b>Pole Num:</b>	<b>Quad Map:</b>	<b>Removal #:</b> 3870620	<b>mer Name/Phone:</b>				
<b>Comment:</b> P0 SSD 1861 RDSD A/F 3 P6 6S/N OWNER @													
									<u>Audit</u>		<i>Last Edit: 7/21/2016 2:02:55 PM by:</i>		
<b>Tree Number</b>  1	<b>Tree Species:</b> Valley Oak	<b>Crew:</b> CA	<b>Priority:</b> Routine	<b>TGR:</b> No	<b>Owned By:</b> Private	<b>Height DBH</b> 90 22	<b>Clearance Prox:</b> 99 Inside	<b>Cycle:</b> Rtn	<b>Qty:</b> 1	<b>Trim Type:</b> FP-Ov B	<b>Account:</b> Y	<b>Wire Conditions:</b>	<b>Insp Date:</b> 5/2/2016 12:01:24 PM
	<b>Comment:</b> .1S N/OF P6 E/OF LINES					<b>Notification:</b> OK	<b>Work Request:</b> Y SNV1000531		<b>WC Date:</b> 8/8/2016	<b>WC Qty:</b> 1	<b>WC Trim:</b> FOB	<b>Completed By:</b>	<b>Invoice:</b> BO (104)
	<b>Lat/Long:</b> 40.50509, -122.570073333 <u>Google Map!</u>				<b>External TreeID:</b>						<u>Audit</u>	<b>Last Edit:</b> 7/21/2016 2:02:55 PM by:	
	<b>Rx Comment:</b>												



# **EXHIBIT A-32**

**Search** **Print**

**North Valley Division - Distribution (YS - 137636)**

**Work Request:** YSNV1000531

**Contractor:** Davey Tree- Sent to Contractor. **Order No:** 8082293

**Date Issued:** 7/27/2016 3:19:31 PM

**Completed:** 8/8/2016 By: [REDACTED]



Circuit: GIRVAN 1101 - (0103401101)

1.) 1 FP-Ov 1 FP-Ov 8/8/16 By: [REDACTED] r Invoiced

**Units Assigned: 1.0**

**Units Completed: 1.0 - ( 100.0% )**

**!** - Indicates that some of the work completed is different than what was assigned.  
**r** - Revised. Record has been billed and then updated by contractor.



PG&E Vegetation Management - VMS Database.

This Report was created on: 3/2/2021 9:06:13 AM.